

# ChangAn VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/ChangAn/Changan passenger vehicle/Fuel vehicle  
model/CS85/CS85 COUPE (2021)/  
VIN: LS4ASE2A9NP136662

Odometer Reading: 166571km

License Plate: --

## Customer Information

Name: --

Tel: --

## Device information

Scanner: MaxiSys MS908S PRO

Version: V13.50

Serial Number: V59SNBC01038

Repair Order Number: --



## System Scanned ( 22 )

| System                                                                      |      | Status/DTC |
|-----------------------------------------------------------------------------|------|------------|
| ECM (Engine system)-MED17810 - UAES                                         |      | ✓ 0        |
| AT (Automatic transmission system)-AT (Automatic Transmission) - Aisin, 8AT |      | ✓ 0        |
| ESP (Electronic stability program)                                          |      | ✗ 1        |
| SRS (Supplementary restraint system)                                        |      | ✓ 0        |
| EDR (Event Data Recorder)-Read Event Data Recorder (EDR) (EDR_213 byte)     |      | ✓ 0        |
| ICM (Instrument cluster system)                                             |      | ✓ 0        |
| AC (Air conditioning system)                                                |      | ✗ 1        |
| ACC (Adaptive cruise control)                                               | ADAS | ✗ 5        |
| APA (Auto parking assist control module)                                    | ADAS | ✗ 3        |
| AVM (All view module)                                                       | ADAS | ✗ 2        |
| BCM (Body control system)                                                   |      | ✗ 18       |
| EPS (Electric Power Steering)                                               |      | ✓ 0        |
| GW (Gateway system)                                                         |      | ✗ 1        |
| DVD (On-board entertainment system)                                         |      | ✗ 1        |
| LCDAL (BLIS [left radar])                                                   | ADAS | ✓ 0        |
| LCDAR (BLIS [right radar])                                                  | ADAS | ✓ 0        |
| PTS (Power tailgate)                                                        |      | ✗ 1        |
| DSM (Driver Seat Module)                                                    |      | ✓ 0        |

|                                                                         |     |
|-------------------------------------------------------------------------|-----|
| ACM (Actuator control)-ACM (Actuator Control Module) (8AT transmission) | ✓ 0 |
| ESL (Shift operation assembly)                                          | ✓ 0 |
| SAS (Steering Angle Sensor)                                             | ✓ 0 |
| board entertainment system)                                             | ✗ 1 |

## DTC ( 33 )

### ESP (Electronic stability program) ( 1 DTC )

| DTC     | Description                       | Status             |
|---------|-----------------------------------|--------------------|
| U210700 | Network diagnosis voltage too low | Current fault code |

### AC (Air conditioning system) ( 1 DTC )

| DTC     | Description                                 | Status             |
|---------|---------------------------------------------|--------------------|
| B140715 | AQS sensor open circuit or short to battery | Current fault code |

### ACC (Adaptive cruise control) ( 5 DTCs )

| DTC     | Description                                          | Status              |
|---------|------------------------------------------------------|---------------------|
| B211477 | ESP indicates its deceleration control not available | Historic fault code |
| B211708 | ESP finds ACC message error                          | Historic fault code |
| B212081 | Body stability control system fault                  | Historic fault code |
| B211881 | Esp's AEB or AWB or ABA or ABP module not available  | Historic fault code |
| U170016 | ACC monitors supply voltage too low                  | Historic fault code |

### APA (Auto parking assist control module) ( 3 DTCs )

| DTC     | Description                                          | Status              |
|---------|------------------------------------------------------|---------------------|
| U14830A | EMS torque request unavailable                       | Historic fault code |
| U14870A | Electronic stability program (ESP) function abnormal | Historic fault code |
| U148E04 | Transmission failure                                 | Historic fault code |

### AVM (All view module) ( 2 DTCs )

| DTC     | Description                       | Status              |
|---------|-----------------------------------|---------------------|
| B230016 | Low power voltage alarm           | Historic fault code |
| U19A586 | Brake pedal status signal failure | Historic fault code |

### BCM (Body control system) ( 18 DTCs )

| DTC     | Description                                     | Status             |
|---------|-------------------------------------------------|--------------------|
| B104015 | Right low beam circuit open or short to battery | Current fault code |
| B104D16 | Battery voltage too low                         | Current fault code |
| B105823 | Overtaking lamp switch stuck                    | Current fault code |
| B106F00 | Front wiper overall failure: wiper stuck        | Current fault code |

|         |                                         |                    |
|---------|-----------------------------------------|--------------------|
| B107102 | Front left tire: low pressure           | Current fault code |
| B107202 | Front right tire: low pressure          | Current fault code |
| B107302 | Rear left tire: low pressure            | Current fault code |
| B107402 | Rear right tire: low pressure           | Current fault code |
| B107993 | Left front tire sensor lost             | Current fault code |
| B107A93 | Right front tire sensor lost            | Current fault code |
| U102F87 | CAN message 0x3b2 timeout               | Current fault code |
| U100A87 | CAN message 0x280 timeout               | Current fault code |
| U101587 | Please refer to vehicle service manual. | Current fault code |
| U101C87 | CAN message 0x2A8 timeout               | Current fault code |
| U102187 | CAN message 0x3b1 timeout               | Current fault code |
| U100381 | LIN3 RLS feedback error                 | Current fault code |
| U10004B | Rain/Light Sensor (RLS) overtemperature | Current fault code |
| U101B85 | RKE key low battery                     | Current fault code |

#### GW (Gateway system) ( 1 DTC )

| DTC     | Description          | Status             |
|---------|----------------------|--------------------|
| U140C81 | Instrument node lost | Current fault code |

#### PTS (Power tailgate) ( 1 DTC )

| DTC     | Description                    | Status              |
|---------|--------------------------------|---------------------|
| B14A667 | Lock switch status not matched | Historic fault code |

#### board entertainment system) ( 1 DTC )

| DTC     | Description      | Status             |
|---------|------------------|--------------------|
| U127388 | CAN disconnected | Current fault code |

#### Technician Notes

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.