

ChangAn Vehicle Diagnostic Report

Vehicle Information

--/ChangAn/--/
VIN: LS5A3DKR0RA979781

Odometer Reading: 23808km
License Plate:



Scan to download
PDF

Customer Information

Name: --

Tel: --

Device information

Scanner: MaxiCOM MK808S
Version: V5.50

Serial Number: DK1GS4C02001
Repair Order Number:
DK1GS4C0200120251126034921026

System Scanned (13)

System	Status/DTC
ECM (Engine system)-UD8_NE14 (without gasoline particulate filter function) - UAES	 0
AT (Automatic transmission system)-DCT (Dual Clutch Transmission) 270	 0
ESP (Electronic stability program)-EPBi (Integrated Electronic Parking Brake)/body stability control system	 0
SRS (Supplementary restraint system)	 0
EDR (Event Data Recorder)-Read Event Data Recorder (EDR) (EDR_425 byte)	 0
ICM (Instrument cluster system)-IP (Instrument Panel) (7-inch LCD)	 0
GW (Gateway system)	 0
BCM (Body control system)-IBCM (Intelligent Body Control Module) - Delphi	 85
RRS (Reverse radar system)	 0
DVD (On-board entertainment system)-HU (Head Unit) (10-inch screen)	 0
ACC (Adaptive cruise control)	 1
EPS (Electric Power Steering)	 0
SLCM (Window Ripple Anti-pinch)	 0

DTC (86)

BCM (Body control system)-IBCM (Intelligent Body Control Module) - Delphi (85 DTCs)

DTC	Description	Status
B100212	Remote access window down circuit short to battery	
B100313	Ignition 2 relay control circuit short open	
B100412	Rear defroster relay circuit short to battery	
B100612	Front wiper speed regulator relay circuit short to battery	
B100712	High beam relay circuit short to battery	
B100812	Remote access window up circuit short to battery	
B100913	Ignition 1 relay control circuit open	
B100A13	Adaptive cruise control (ACC) relay control circuit open	
B100B12	Horn relay circuit short to battery	
B100C12	Headlamp washer relay circuit short to battery	
B100C13	Headlamp washer relay circuit open	
B101412	Front wiper power supply relay circuit short to battery	
B101512	Rear wiper relay circuit short to battery	
B101612	Marker lamp relay circuit short to battery	
B101712	Hidden door handle folding circuit short to power supply	
B101812	Hidden door handle unfolding motor output circuit is short-circuited to the power supply	
B102012	Anti-theft indicator lamp circuit short to battery	
B102111	Mirror folded circuit short to ground	
B102211	Mirror unfolded circuit short to ground	
B102411	Left rear fog lamp circuit short to ground	
B102711	Starter relay control circuit short to ground	
B102713	Start relay control circuit open fault	
B102811	Rear right fog lamp short to ground	
B102813	Right rear fog lamp circuit open	
B102A11	Start/stop switch light (green) circuit short to ground	
B103111	Reverse light short to ground	
B103311	Right turn light short to ground	
B103313	Right turn lamp circuit open	
B103318	Right turn light operation interrupted	
B103413	Trunk open circuit open (to battery 7)	
B103513	Driver door not locked - circuit open (to battery 8)	
B103613	Passenger door not locked - circuit open (to battery 8)	

B103713	All doors locked - circuit open (to battery 8)
B103813	Fuel pump pressure setting relay circuit open (to battery 7 or battery 6 according to vehicle settings)
B103911	Left side turn light circuit short to ground
B103913	Left turn signal light open circuit
B103918	Left turn light broken
B103A11	Front left fog lamp short to ground
B103A13	Left front fog light open
B103C11	Left low beam lamp circuit short to ground
B104011	Right low beam lamp circuit short to ground
B104311	Front right fog lamp circuit short to ground
B104313	Right front fog lamp circuit open
B104412	Energy saving supply, battery circuit short
B105C29	Fog lamp combination switch status error
B106012	Start/stop switch 1 circuit short to battery
B106112	Start/stop switch 2 circuit short to battery
B106211	Start/stop switch 1 inconsistent with start/stop switch 2
B106929	Front wiper switch status error
B108541	Body control module (BCM) keep alive memory (KAM) error
B108641	ECU flash error
B108741	ECU EEPROM error
B108941	ECU stack overflow
U100286	LIN2 Driver Door Control Unit (DDCU) signal error
U100387	LIN3 RLS communication timeout
U100A01	Reverse radar system failure
U100B87	CAN message 0x276 timeout
U101787	BCM network management limp home failure
U101883	EMS immobilizer verification request frame checksum error
U101987	Verification request of EMS immobilizer not received
U101A87	Verification result of EMS immobilizer not received
U101B44	Remote Key EEPROM Error
U101B85	RKE key low battery
U101B86	Remote access key signal counter error
U102286	LIN2 Passenger Door Control Unit (PDCU) signal error

U102386	LIN 2 RLCU signal error
U102486	LIN 2 RRCU signal error
U102586	LIN 2 sunroof signal error
U102686	Please refer to vehicle service manual.
U102786	LIN2 dome signal error
U102987	LIN2 RLDCU communication timeout
U102E87	CAN message 0x3b1 timeout
U102F87	CAN message 0x3b2 timeout
U103081	LIN 2 RPAS_LIN feedback error
U103786	Window switch signal error
U103D87	Intelligent Battery Sensor (IBS) communication lost
U103E87	LIN 2 reversing radar communication timeout
B100512	High-voltage fuel tank cap relay short circuit to battery
B102E11	Trunk light short to ground
B102E13	Trunk lamp circuit open
B103211	Brake lamp circuit short to ground
B103B11	High-mounted stop lamp short to ground
B103D12	Interior lamp battery circuit short
B102311	Left DRL circuit short to ground
B104211	Right DRL circuit short to ground

ACC (Adaptive cruise control) (1 DTC)

DTC	Description	Status
B212578	ACC not calibrated or calibration offset too large	Current fault code

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.